Qtv:

50 Um:

Each

: BASKET HINGE

: D22323

: N/A

: D2232 REV C

: 05/11/2006

Thursday, 26/10/2006 1:18:50 PM

Linda Lacelle

Process Sheet

Drawing Name

Part Number

Material **Due Date**

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 29132

Estimate Number P.O. Number

: 10588

AIG:

This Issue Prsht Rev.

First Issue

: 26/10/2006

: NC

: NIA

Type

: SMALL /MED FAB

S.O. No. : 1/1/A

: 29132 **Previous Run**

Written By

Checked & Approved By

Comment

Now laser cut EC Est Rev:C Now on Wateriet 06-10-26 JLM

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

M304S11GA

Comment: Qty.: 0.0729 sf(s)/Unit Total: 304/316 .125 Sheet

3.6435 sf(s)

Batch: 101463

304/316 .125 Sheet

2.0

WATER JET

Comment: FLOW WATER JET


1-Cut as per Dwg D2232

Dwg Rev:_ Prog Rev:__



2-Deburr if necessary

3.0 QC2



INSPECT PARTS AS THEY COME OFF MACHINE

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK



Comment: SECOND

5.0

SMALL & MEDIUM FAB RESOURCE 1



SMALL FAB 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr

SAD 00:11:06

	The state of the s		1 8
i.			Ý
€ 2		8)	
· ·			
			3
	3.9		
4			
\$ \$			
	199		•
yd danna.			
			• * •
			•
	. V. desiler		
Salar v and a second	Secretary and the second secon		and the second s

Date:

Thursday, 26/10/2006 1:18:50 PM

User: •

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BASKET HINGE

Part Number: D22323

Job Number:

Job Number: 29132

Seq. #:

Machine Or Operation:

Description:

6.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock Location: 105

7.0

QC21



FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE



Job Completion



4 de((1.0)

Tuesday, 10/24/2006 11:02:26 AM Kim Johnston /User: **Process Sheet** : BASKET HINGE : CU-DAR001 Dart Helicopters Services **Drawing Name** Customer : 29132 Job Number : 10588 **Estimate Number** : D22323 Part Number P.O. Number : D2232 REV C : 10/24/2006 S.O. No. : **Drawing Number** This Issue Prsht Rev. : NC Project Number : N/A : // : PURCHASED PARTS : C Type Drawing Revision First Issue : 25239 Material **Previous Run** 50 Um: Each : 11/5/2006 Qty: **Due Date** Written By Checked & Approved By : Est. Now laser cut EC Comment **Additional Product** Job Number: Description: Machine Or Operation: Seq. #: **PURCHASING** 1.0 Comment: PURCHASING Issue P/O:_ Laser cut as per DWG D2232 Material: 304/316 ss 0.125 \text{\thick} Material release note attached D22323F 2.0 1.0000 Each(s)/Unit Total: 50.0000 Each(s) Comment: Qty.: **Basket Hinge** PACKAGING 1 PACKAGING RESOURCE #1 3.0 Comment: PACKAGING RESOURCE #1 Recieive & Inspect for Transit Damage Ensure Material Release Note is attached DIMENSIONAL CHECK 4.0 QC6 Comment: DIMENSIONAL CHECK SMALL & MEDIUM FAB RESOURCE 5.0 SMALL FAB 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Deburr

Dart Aerospace Ltd

	. оориоо -									
W/O:			WC	ORK ORDER CHAN	GES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
3										
D- 4 N-										
Part No	:	PAR #: Fault Category:							Date: Date:	
NCR:			WORK ORDI	ER NON-CONFORM	IANCE	(NCR				
DATE	STEP	Description of NC		Corrective Action Section B Initial Action Description				cation	Approval	Approval
	-2.	Section A	Chief Eng	Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector
										H
										Y.*

NOTE: Date & initial all entries

Date: User: Tuesday, 10/24/2006 11:02:27 AM

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BASKET HINGE

Job Number: 29132

Part Number: D22323

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

7.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:_

QC21

FINAL INSPECTION/W/O RELEASE




Comment: FINAL INSPECTION/W/O RELEASE


Job Completion



Dart Ae	rospace i	_ta								
W/O:			WC	RK ORDER CHANG	GES					i
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Cateç	jory:	NCF	R: Yes	No DQ /	A:	Date:	
						QA: N	C Close	d:	_ Date: _	
NCR:		-	WORK ORDE	R NON-CONFORM	ANCE	(NCR)			
DATE	STEP	Description of NC	Description of NC Corrective Action		Section B		Verific	ation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
								•		
			-							
				ec.						_
		19								_

NOTE: Date & initial all entries





Work Order:	29132
Part Number:	D5939-3
	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

	1		
X	First Article	X	Prototype

Drawing	Tolerance	Actual	Accept	Reject	Method of Inspection	Comments
Dimension	4	Dimension		Reject	" (Spection	
0.500	H-0.010	0.500	1		verN	
0.750	41-0.010	0.750	V		N2.9V	
2.500	41-0.010	2.509	Y		Vern	·
1.000	11-0.010	1.000	٧	•	Y TW-N	
0.750	4-0.010	0.750	.~		Vern	
2.250	+1-0.010	2.250	5		vern	
0.500	11-0.010	0.50/	/		vern	•
Ø 0.257	100.006-0.001	0.256	1		verN	
					-	350
	4					
	· ·					
				4.1		
				1 5		
			•			
						•
					.4	
						

Measured by:	m M	Audited by:	Prototype Approval:
Date:	06 11 06	Date: 06/11/06	Date:
		97:/5	

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	j

